

IF YOU START IT-FINISH IT!



On a UH-60, the drive shaft was removed and hardware placed inside the drive shaft. A different mechanic installed the drive shaft and did not know the hardware was inside. The aircraft was run up and the inside of the drive shaft was severely damaged. **IF YOU START IT-FINISH IT!**